Oil Field Environmental Incident Summary Incident: 20141012162047 **Date/Time of Notice:** 10/12/2014 16:20 Responsible Party: CONTINENTAL RESOURCES, INC. CONTINENTAL RESOURCES, INC. Well Name: PIERRE 1-21H Field Name: DOLLAR JOE Well File #: 21030 **Date Incident: 10/12/2014 Time Incident:** 08:00 Facility ID Number: **WILLIAMS Twp:** 155 **Rna**: 97 Sec: 21 Qtr: County: Location Description: Submitted By: Patrick Skillestad Received By: Contact Person: Patrick Skillestad PO BOX 268870 OKLAHOMA CITY, OK 73126 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Other Release Contained in Dike: Yes - Within Dike Reported to NRC: No Spilled Units Recovered Units Followup **Units** Barrels 1.5 Oil 1.5 Barrels **Brine** Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation:

Areal Extent:

None

Potential Environmental Impacts:

Soil in flare pit.

Action Taken or Planned:

Sucked up standing fluid and returned to oil tanks.

Wastes Disposal Location: Production tanks onsite.

Agencies Involved:

Updates

Date: 10/13/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release due to treater upset. Oil was directed to the flare pit, and it remained on location within the flare pit diking according to the report. NDIC retains oversight.